

# AIR-ASSISTED AIRLESS NOZZLES - SIZES AVAILABLE



## MIX NOZZLE TYPE WAGNER

WGMXXX

Example: For a tip with .011mm and angle 30° order WGM311  
 Sizes available in the following table. More sizes available on request

IN	MM	Angle	.007	.009	.011	.013	.015	.017	.019	.021
2-4	(50-102)	10°	107	109	111					
4-6	(102-152)	20°	207	209	211	213	215	217	219	221
6-8	(152-203)	30°	307	309	311	313	315	317	319	321
8-10	(203-254)	40°		409	411	413	415	417	419	421
10-12	(254-305)	50°		509	511	513	515	517	519	521
12-14	(305-356)	60°		609	611	613	615	617	619	621
14-16	(356-406)	70°			711	713	715	717	719	721
16-18	(406-457)	80°					815	817	819	821
18-20	(457-508)	90°						917	919	921



## MIX NOZZLE TYPE WAGNER WITH PRE-ORIFICE

WGM2XXX

Example: For a tip with .010mm and angle 30° order WGM2310  
 Sizes available in the following table. More sizes available on request

IN	MM	Angle	.008	.010	.012	.014	.016
4-6	(102-152)	20°	208	210	212		
6-8	(152-203)	30°	308	310	312		
8-10	(203-254)	40°	408	410	412	414	416
10-12	(254-305)	50°		510	512	514	516
12-14	(305-356)	60°		610	612	614	616
14-16	(356-406)	70°		710	712	714	716